

TRF796x Software Design Hints

1 Software Design Hints

Table 1 shows which items apply to each device.

Table 1. Device Application

Item	TRF7960	TRF7961
#1 ISO15693 only - Direct command (0x14) 'Transmit next slot'	✓	✓
#2 Missing IRQ	✓	✓
#3 Lost IRQ	✓	✓
#4 Wrong data due to "overshoots"	✓	
#5 ISO14443A decoder	✓	
#6 Tags that do not follow the 14443A-level 4 framing	✓	
#7 SPI specialties / typical pitfalls	✓	✓

#1 **ISO15693 only - Direct command (0x14) 'Transmit next slot'**

Description

Sending of 'Transmit next slot' direct command (0x14) can happen only once (ISO 15693).

Hint

Before sending the 'Transmit next slot' direct command, the 'Reset' direct command must be sent.

Used only in ISO 15693 'Inventory' command (with 16 time slots). ISO 15693 'Write Single Block' command and 'Lock Block' command are affected also if the 'Option' bit is set.

#2 **Missing IRQ**

Description

The device does not send (by pin 13) any interrupt requests on certain conditions. The chip can enter a state in which the sending of additional interrupts during receive (RX) or transmit (TX) is stopped. This happens when the Stop Condition is exactly aligned with the byte boundary on the TX data.

Hint

The loading and reading of the FIFO should be coded so that the Stop Condition does not fall directly on the TX byte boundary.

#3 **Lost IRQ**

Description

Lost IRQ if the end of RX IRQ arrives at the same time that the IRQ register is being read (also see #6).

Hint

Add additional checks to retrieve the RX data if the IRQ is suppressed by a coinciding read operation.

#4	<i>Wrong data due to "overshoots"</i>
Description	The 14443A 106-kbps decoder gives wrong data in certain condition. When the analogue front-end filter overshoots, the digitizer might produce a rising edge on the subcarrier data. If this occurs within a small time window, the decoder produces false data. This happens extremely rarely and is dependent on the antenna and filter characteristics.
Hint	Switch to PM channel or adjust gain to avoid overshoots in the analogue filter.
#5	<i>ISO14443A decoder</i>
Description	ISO14443A subcarrier decoder makes a wrong decoding – "reading holes".
Hint	Repeating the reading using different gain setting of PM channel results in correct data read; this might require additional time.
#6	<i>Tags that do not follow the 14443A-level 4 framing</i>
Description	When a transmit frame starts with the code 0x93, 0x95, or 0x97, the reply is not correctly framed. This happens because the TRF796x devices have an automatic ANTICOLLISION broken byte framer that is activated with the 0x93, 0x95, or 0x97 code.
Hint	Use TRF7960 "Direct Mode".
#7	<i>Errata TRF796x – SPI specialties / typical pitfalls</i>
	For further information concerning the SPI, see <i>Using the SPI interface with the TRF7960</i> (SLOA140).
#7a	<i>SPI with SS pin only – no high impedance</i>
Description	Serial interface with SS pin only. The interface does not go to high impedance when SS is high. It is not possible to multiplex the serial port interface lines.
Hint	An external three-state buffer must be used if the chip is connected to a serial bus and the interface lines need to be multiplexed.
#7b	<i>SPI with SS pin only – direct commands</i>
Description	Serial interface with SS pin only. The direct commands are not executed if they are the last operation in the SPI communication. In the SPI interface with SS pin, the Stop condition clock pulse is missing (compared to the parallel interface and SPI without SS pin). Some operations rely on this clock, and they do not work as expected.
Hint	If a direct command is the last operation in the SPI communication (the SS pins goes high after) an additional clock pulse must be sent.

#7c	<i>SPI with SS pin only – IRQ status bit</i>
Description	Serial interface with SS pin only. IRQ status bits are not cleared after the 'IRQ status' register (0x0C) is read.
Hint	A dummy read must be made after reading the 'IRQ status' register. This can be done in noncontinuous or continuous mode. In continuous mode, 8 clock pulses are needed. In noncontinuous mode, 16 clock pulses are needed (8 pulses for address and 8 pulses for data).
#7d	<i>SPI with SS pin only – no TX if single bit in FIFO</i>
Description	Serial interface with SS pin only. The chip does not start with transmission if only 1 byte is loaded to the FIFO.
Hint	The microcontroller must load an additional byte to the FIFO. The chip transmits only 1 byte on the TX if the "Number of complete bytes" in the registers 0x1D and 0x1E is 1.
#7e	<i>SPI with SS pin only – clock polarity change</i>
Description	Data CLK clock polarity must be switched when FIFO read operation (single or continues) is executed. During SPI data transmission, the MOSI line is valid on the rising edge, and the MISO line is valid on the falling edge of the Data CLK signal.
Hint	Firmware must switch clock polarity between FIFO writes and reads.
#7f	<i>SPI with SS pin only – IRQ status register rst</i>
Description	The IRQ Status register (0x0C) is not automatically cleared after reading.
Hint	A dummy register read is required to clear the content of the IRS status register and drive the IRQ line to low.
#7g	<i>SPI with SS pin only – Single byte Direct commands</i>
Description	All single byte direct commands need an additional CLK cycle to work.
Hint	All direct command functions must have an additional Data CLK cycle before SS goes high.
#7h	<i>SPI with SS pin only – some registers do not take default values</i>
Description	Some of the registers do not take the default values when the appropriate protocol is chosen in the ISO Control register.
Hint	Manually program the default settings into the TRF796x during initialization.

2 TRF796x – Known Issues With Specific Tags

Table 2. Known Issues

Issue Number	Tag Type	Problem	Hint
T1	MIFARE™ Ultralight	The 4-bit ACK and NAK reply can not be decoded with the integrated decoder/framer system. The 4-bit ACK is not according the standard ISO 14443A, so the internal data framing reports an error and needs to be by-passed.	Direct mode
T2	MIFARE Classic (standard)	The parity check fails with the encrypted frames as the MIFARE standard encrypts also the parity bit.	Direct mode
T3	Tags that do not follow the 14443A-level 4 framing	When a transmit frame starts with the code 0x93, 0x95, or 0x97, the reply is not correctly framed. This happens because the TRF796x devices have an automatic ANTICOLLISION broken byte framer that is activated with the 0x93, 0x95, or 0x97 code.	Direct mode
T4	Cryptography cards like JCOP, DESFire™	Using a cryptography card (for example, JCOP or DESFire) at close proximity (<1 cm) can cause a wrong collision error detection.	The reason is the 'calculation noise' emitted by the card which can be suppressed if the gain is drastically reduced. We proposed to use addition gain reduction enabled by test register.
T5	ISO 15693 cards requiring a slot delimiter (EOF)	There are ISO15693 cards on the market that require a slot delimiter (EOF).	A dedicated MCU timer needs to be used to generate the 37.76-μs timing grid.

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products		Applications	
Amplifiers	amplifier.ti.com	Audio	www.ti.com/audio
Data Converters	dataconverter.ti.com	Automotive	www.ti.com/automotive
DLP® Products	www.dlp.com	Communications and Telecom	www.ti.com/communications
DSP	dsp.ti.com	Computers and Peripherals	www.ti.com/computers
Clocks and Timers	www.ti.com/clocks	Consumer Electronics	www.ti.com/consumer-apps
Interface	interface.ti.com	Energy	www.ti.com/energy
Logic	logic.ti.com	Industrial	www.ti.com/industrial
Power Mgmt	power.ti.com	Medical	www.ti.com/medical
Microcontrollers	microcontroller.ti.com	Security	www.ti.com/security
RFID	www.ti-rfid.com	Space, Avionics & Defense	www.ti.com/space-avionics-defense
RF/IF and ZigBee® Solutions	www.ti.com/lprf	Video and Imaging	www.ti.com/video
		Wireless	www.ti.com/wireless-apps

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2010, Texas Instruments Incorporated