

Hercules™ Software Diagnostic Library CSP Without

Contents

1	New in this release
2	Folder Structure
3	Contents of CSP
4	Fixed in This Release
5	Known Issues
	List of Tables
1	Fixed in This Release
2	Summary of Known Issues

Trademarks

Hercules is a trademark of Texas Instruments.

1 New in this release

The following outlines the defects resolved and enhancements done in this release:

 Updated CSP for Hercules Software Diagnostic Library to 2.4.0 release – static analysis of source code has been updated to 2.4.0 source code.

To re-run the unit tests using the included Test Automation Unit (TAU) software, customers are required to purchase and install LDRA Unit software from LDRA.

2 Folder Structure

The installer for this software installs by default to the C:\ti\Hercules folder. The folder structure is as shown below:

```
C:\ti\Hercules\SafeTI Diagnostic Library\ Installation Root folder
2.4.0
                                           Product version number
    +---build\
                                           Project files for demo
                                           application (Device specific)
    +---build_safeTILib
                                           Project file for building library
    +---build_TPSDriverLib
                                           Project file for building TPS Driver library
    +---demo_app\
                                           Demo application
        +---common\
                                           Source code
        \---HALCoGen\
                                           HALCoGen configuration
                                           (Device specific)
    +---docs
                                           Documentation.
    +---hal
                                           Device hardware abstraction
    +---libs
                                           Prebuilt libraries
    +---safety_library
                                           Source code for Diagnostic
                                           Library
                                           Test automation unit for testing the API.
    +---Test
```



Contents of CSP www.ti.com

\---TPS_driver

Source code for the TPS65381 Driver

3 Contents of CSP

- · Quality Review Report HIS Metrics
- Code Review Report MISRA C compliance report
- Test results Report
- Traceability report
- Software user guides
- · Software release Note
- Software safety requirements document
- · Software architecture document
- Software design document
- · Software safety manual

4 Fixed in This Release

Table 1. Fixed in This Release

References	Headline	Description
SDOCM00122361	Clearly document what was tested and what wasn't tested with a certain release.	Issue Details: Clearly document which of the following certain releases was tested: MCU's, Kit's, CCS/Compiler Version, IAR Version A matrix to see which combinations were tested and are supported would really help. Implementation Information: Updated user's guide and safety manual to document the devices tested against, and compiler tool chains with their versions.
SDOCM00122862	Static analysis shows errors for RM42x/TMS570LS04x/03x and RM46x/TMS570LS12x/11x devices.	Issue Details: Static analysis shows errors for RM42x/TMS570LS04x/03x and RM46x/TMS570LS12x/11x devices. Implementation Information: Upon running static analysis for these platforms, we get errors for RM42x/TMS570LS04x/03x and RM46x/TMS570LS12x/11x devices. For RM46x/TMS50LS12x/11x: These were because of code specific to these platforms not having appropriate justification. For RM42x/TMS50LS04x/03x: These were because of code not specific to these platforms is not disabled with compile time switches.

2



www.ti.com Known Issues

5 Known Issues

Table 2. Summary of Known Issues

Title Pag	е	
HERCULES_SW-5194 —FLASH_ADDRESS_PARITY_SELF_TEST fails on LDRA unit testing for RM42x and TMS570LS04x platform		
HERCULES_SW-5196 — SCI and LIN modules untested by LDRA unit testing		
HERCULES_SW-5113 —TPS-Driver - Reset on enabling a ABIST and LBIST Run		
HERCULES_SW-5126 —TPS_GetWatchdogFailureStatus giving failure status as TRUE when Watchdog fail count is 7 and Watchdog reset is not enabled		
HERCULES_SW-5147 — MISRA-C violation detected incorrectly in TPS_Interface.c		
1 —Test case with ID "VIM2A:10" in VIM_UT.xlsx fails		
2 — Data-Abort-exception handler code causes test failure		
3 —Test Report Consolidation script unavailable in CSP 5		

HERCULES_SW-5194 FLASH_ADDRESS_PARITY_SELF_TEST fails on LDRA unit testing for RM42x and TMS570LS04x platform.

Issue details FLASH_ADDRESS_PARITY_SELF_TEST fails on unit testing for diagnostic functionality

on RM42x and TMS570LS04x platform.

Devices All RM42x and TMS570LS04x device platforms

Workaround For the test case identified as "FLA4:1", used to test SL SelfTest Flash() to execute

properly, sys_startup.c in RM42x and TMS570LS04x SDL TAU should be updated with a code that updates memory region pointed by 'ulHighHandlerStartAddr' with contents

from memory address given by 'ulHighHandlerLoadStart' with copy size as

'ulHighHandlerSize'.

User can download the corrected sys_startup.c file from the following link and replace

the existing file in CSP before testing with LDRA: http://www.ti.com/tool/SAFETI-

HERCULES-DIAG-LIB-CSP.

HERCULES_SW-5196 SCI and LIN modules untested by LDRA unit testing

Issue details Software Diagnostic Library product version 2.4.0 does not have unit testing

implemented for SCI and LIN module - Cannot test SCI/LIN as the SCI port is used as

UART for sending LDRA data to the PC.

Devices All device platforms

Workaround None

HERCULES SW-5113 TPS-Driver - Reset on enabling a ABIST and LBIST Run.

Issue details Power reset is observed when enabling the ABIST/LBIST run by writing the LBIST_EN

and ABIST_EN bits in the safety_bist_ctrl register of the TPS device.

Devices All device platforms

Workaround ABIST and LBIST must be run independently. Trying to run both ABIST and LBIST at

the same time is not allowed.



HERCULES_SW-5126 — TPS_GetWatchdogFailureStatus giving failure status as TRUE when Watchdog fail count is 7 and Watchdog reset is not enabled www.ti.com

HERCULES_SW-5126 TPS_GetWatchdogFailureStatus giving failure status as TRUE when Watchdog fail count is 7 and Watchdog reset is not enabled

Issue details The API TPS_GetWatchdogFailureStatus should return the failure status as true only

when the watchdog failure count is 7 and the watchdog reset is enabled. But the failure status is returned as TRUE even when the watchdog failure count is 7 and watchdog

reset is not enabled.

Devices All device platforms

Workaround The TPS65381A-Q1 datasheet has been updated to provide clarity on the working of the

watchdog. When the fail counter reaches 7, device will not cause a RESET. The counter on reaching 7+1(or the next bad event after it has reached 7) will put the device to

RESET state.

HERCULES SW-5147 MISRA-C violation detected incorrectly in TPS Interface.c

Release Note Incorrect violations in TPS driver detected in LDRA

Devices All device platforms

Workaround None

1 Test case with ID "VIM2A:10" in VIM_UT.xlsx fails

In SL_SelfTest_PBIST() in previous version of SDL, there was a if statement check for

nERROR_Active status as TRUE and so a test case was specifically added to test this block of code. The nERROR_Active status check is removed from the code in latest

version, and so the test case is no more valid but causes failure.

Devices All device platforms

Workaround The test case, identified as "VIM2A:10", used to test SL_SelfTest_PBIST() should be

removed from VIM UT.xlsx before performing VIM Unit Test.

User can download the corrected VIM_UT.xlsx file from the following link and replace the

existing file in CSP before testing with LDRA: http://www.ti.com/tool/SAFETI-

HERCULES-DIAG-LIB-CSP.

2 Data-Abort-exception handler code causes test failure

Issue details Test case fails due to _excpt_vec_abort_data() because of one missing condition check

for FLASH ADDRESS ECC SELF TEST status, during Flash status checks.

Devices All device platforms

Workaround Change the if-statement @ line 171 in exception_handlers.c from:

if (((TRUE == SL_FLAG_GET(FLASH_ECC_TEST_MODE_2BIT))))||(TRUE ==

SL_FLAG_GET(FLASH_ECC_ADDR_TAG_REG_MODE)))

To:

if (((TRUE == SL_FLAG_GET(FLASH_ECC_TEST_MODE_2BIT)))||(TRUE ==

SL_FLAG_GET(FLASH_ADDRESS_ECC_SELF_TEST))||(TRUE ==

SL_FLAG_GET(FLASH_ECC_ADDR_TAG_REG_MODE)))

User can download the corrected exceptions_handlers.c file from the following link and replace the existing file in CSP before testing with LDRA: http://www.ti.com/tool/SAFETI-

HERCULES-DIAG-LIB-CSP.



3 Test Report Consolidation script unavailable in CSP

Issue details Batch Script file used to consolidate Test Reports is not added in CSP.

Devices All device platforms

Workaround The Batch Script file is uploaded onto a TI web-page and the link to download the file is

given below.

User can download the Batch Script file from the following link and copy it in the installed CSP's directory in Test\Misc\Scripts: http://www.ti.com/tool/SAFETI-HERCULES-DIAG-

JB-CSP.

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

Tl's products are provided subject to Tl's Terms of Sale (www.ti.com/legal/termsofsale.html) or other applicable terms available either on ti.com or provided in conjunction with such Tl products. Tl's provision of these resources does not expand or otherwise alter Tl's applicable warranties or warranty disclaimers for Tl products.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2020, Texas Instruments Incorporated