



Nicholas Oborny

“Magic smoke” is an informal term for the caustic smoke produced by overheated electronic circuits and components. These words have been spoken by almost every electrical engineer, often when they forgot to adjust the power-supply voltage level or accidentally shorted the voltage rail to a logic pin.

The technical reason for this event is electrical overstress (EOS); while human error is a common source, there are other, more subtle possible causes. EOS is often behind some of the most common questions posted to the [TI E2E™ Community Motor Drive forum](#), including those that begin with: “My motor driver has stopped working correctly,” “My motor driver is damaged,” and “My motor is no longer spinning.” I will outline what EOS is and list a few common sources of EOS in motor-drive systems. In my next post, I will discuss several methods to help you prevent EOS in motor-drive systems.

EOS is thermal damage that occurs when an electronic device is subjected to a current or voltage beyond that device’s specified limits. Thermal damage typically results from excessive heat generated during the EOS event (high current across a resistance). The high temperature causes damage to the materials used to construct the integrated circuit, resulting in destruction or a permanent change in its operation.

Now that you know what EOS is, how do you know what the specified limits are? For this, you must examine the Absolute Maximum Ratings table in the data sheet of the electronic device (see [Figure 1](#), which is from the [DRV8701 data sheet](#)). The absolute maximum ratings are the specifications beyond which permanent damage can occur. Absolute maximum ratings differ from the recommended operating conditions in a data sheet; if you go outside those specifications, the device may continue to function, just at specifications outside of the datasheet limits. An example of a violation for [Figure 1](#) would be if the VM power-supply pin reached 50 V due to a transient event on the power rail.

## 6.1 Absolute Maximum Ratings

over operating free-air temperature range referenced with respect to GND (unless otherwise noted) <sup>(1)</sup>

	MIN	MAX	UNIT
Power supply voltage (VM)	-0.3	47	V
Power supply voltage ramp rate (VM)	0	2	V/μs
Charge pump voltage (VCP, CPH)	-0.3	VM + 12	V
Charge pump negative switching pin (CPL)	-0.3	VM	V
Internal logic regulator voltage (DVDD)	-0.3	3.8	V
Internal analog regulator voltage (AVDD)	-0.3	5.75	V
Control pin voltage (PH, EN, IN1, IN2, nSLEEP, nFAULT, VREF, IDRIVE, SNSOUT)	-0.3	5.75	V
High-side gate pin voltage (GH1, GH2)	-0.3	VM + 12	V
Continuous phase node pin voltage (SH1, SH2)	-1.2	VM + 1.2	V
Pulsed 10 μs phase node pin voltage (SH1, SH2)	-2.0	VM + 2	V
Low-side gate pin voltage (GL1, GL2)	-0.3	12	V
Continuous shunt amplifier input pin voltage (SP, SN)	-0.5	1	V
Pulsed 10-μs shunt amplifier input pin voltage (SP, SN)	-1	1	V
Shunt amplifier output pin voltage (SO)	-0.3	5.75	V
Open-drain output current (nFAULT, SNSOUT)	0	10	mA
Gate pin source current (GH1, GL1, GH2, GL2)	0	250	mA
Gate pin sink current (GH1, GL1, GH2, GL2)	0	500	mA
Shunt amplifier output pin current (SO)	0	5	mA
Operating junction temperature, T <sub>j</sub>	-40	150	°C
Storage temperature, T <sub>stg</sub>	-65	150	°C

(1) Stresses beyond those listed under *Absolute Maximum Ratings* may cause permanent damage to the device. These are stress ratings only, which do not imply functional operation of the device at these or any other conditions beyond those indicated under *Recommended Operating Conditions*. Exposure to absolute-maximum-rated conditions for extended periods may affect device reliability.

**Figure 1. Absolute Maximum Ratings table for the DRV8701**

So what are some common sources of EOS in motor-drive systems?

## Supply Overvoltage

One of the most common sources of EOS is an overvoltage event on the device's power-supply input. Supply overvoltage can be caused by motor regeneration (as outlined in an earlier post, example in Figure 2) or an external event to the system such as a component failure. Understanding where an overvoltage event originated from requires monitoring the system-supply rail under all possible internal and external operating conditions.




Figure 2. Supply overvoltage transient

## Switching Transients

Another common source of EOS in motor-drive systems is exposure to voltage transients related to the switching of the power MOSFETs. In an ideal half-bridge switching system, the voltage would alternate between ground and the voltage supply (Figure 3). In the real world, however, parasitics in the power MOSFETs and printed circuit board (PCB) layout can cause voltage transients to go below ground or above the voltage supply (Figure 4).




Figure 3. Ideal half-bridge driver




Figure 4. Half-bridge driver with parasitics

### MOSFET Overcurrent

The last EOS event I'll mention is related to overcurrent of the power MOSFET. TI's integrated motor drivers incorporate both overcurrent and overtemperature protection features to prevent EOS from overcurrent conditions. I discussed these in detail in a previous [post](#), but for systems using a gate driver with external power MOSFETs, you must take care not to violate the MOSFET safe operating areas. A power MOSFET data sheet will often incorporate a safe operating area (SOA) curve (shown in [Figure 5](#)). Excessive current in the power MOSFET will eventually lead to thermal damage of the device or its package.




Figure 5. CSD18540Q5B maximum safe operating area

---

In my next post, I will discuss some common solutions to prevent EOS in motor-drive systems. These range from external protection components to simple design considerations. If you would like for me to address something specific about EOS, post a comment below or ask a question in the [TI E2E Community Motor Driver forum](#).

#### **Additional Resources**

- Read other blogs in this series on the [most frequently asked questions](#) from the Motor Driver forum.
- Looking for additional [advice to prevent EOS](#)? Find tips in this Engineer It video.

## IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#) or other applicable terms available either on [ti.com](https://www.ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265  
Copyright © 2023, Texas Instruments Incorporated