# Functional Safety Information

# TCAN1046A-Q1 and TCAN1046AV-Q1 Functional Safety FIT Rate, FMD and Pin FMA



#### **Table of Contents**

1 Overview	2
2 Functional Safety Failure In Time (FIT) Rates	
3 Failure Mode Distribution (FMD)	6
4 Pin Failure Mode Analysis (Pin FMA)	<mark>7</mark>
5 Revision History	12
List of Figures	
Figure 1-1. TCAN1046A-Q1 Functional Block Diagram	3
Figure 1-2. TCAN1046AV-Q1 Functional Block Diagram	4
Figure 4-1. TCAN1046A-Q1 D Package, 14 Pin SOIC, Top View	
Figure 4-2. TCAN1046A-Q1 DMT Package, 14 Pin VSON, Top View	
Figure 4-3. TCAN1046AV-Q1 D Package, 14 Pin SOIC, Top View	
Figure 4-4. TCAN1046AV-Q1 DMT Package, 14 Pin VSON, Top View	8
List of Tables	
Table 2-1. Component Failure Rates per IEC TR 62380 / ISO 26262 Part 11	
Table 2-2. Component Failure Rates per Siemens Norm SN 29500-2	
Table 3-1. Die Failure Modes and Distribution	
Table 4-1. TI Classification of Failure Effects	
Table 4-2. Pin FMA for Device Pins Short-Circuited to Ground	
Table 4-3. Pin FMA for Device Pins Open-Circuited	
Table 4-4. Pin FMA for Device Pins Short-Circuited to Adjacent Pin TCAN1046A-Q1	
Table 4-5. Pin FMA for Device Pins Short-Circuited to Adjacent Pin TCAN1046AV-Q1	
Table 4-6. Pin FMA for Device Pins Short-Circuited to V <sub>CC</sub>	
Table 4-7. PIN FMA for Device Pins Short-Circuited to V <sub>IO</sub>	
Table 4-8. Pin FMA for Device Pins Short-Circuited to V <sub>BAT</sub>	11

#### **Trademarks**

All trademarks are the property of their respective owners.

Overview www.ti.com

#### 1 Overview

This document contains information for TCAN1046A-Q1 and TCAN1046AV-Q1 (VSON, SOIC, and SOT packages) to aid in a functional safety system design. Information provided are:

- Functional Safety Failure In Time (FIT) rates of the semiconductor component estimated by the application of industry reliability standards
- Component failure modes and their distribution (FMD) based on the primary function of the device
- Pin failure mode analysis (Pin FMA)

Figure 1-1 shows the TCAN1046A-Q1 functional block diagram for reference. Figure 1-2 shows the TCAN1046AV-Q1 functional block diagram for reference.

ww.ti.com Overview




Figure 1-1. TCAN1046A-Q1 Functional Block Diagram

Overview INSTRUMENTS

www.ti.com




Figure 1-2. TCAN1046AV-Q1 Functional Block Diagram

TCAN1046A-Q1 and TCAN1046AV-Q1 were developed using a quality-managed development process, but were not developed in accordance with the IEC 61508 or ISO 26262 standards.



## 2 Functional Safety Failure In Time (FIT) Rates

This section provides Functional Safety Failure In Time (FIT) rates for TCAN1046A-Q1 and TCAN1046AV-Q1 based on two different industry-wide used reliability standards:

- Table 2-1 provides FIT rates based on IEC TR 62380 / ISO 26262 part 11
- Table 2-2 provides FIT rates based on the Siemens Norm SN 29500-2

Table 2-1. Component Failure Rates per IEC TR 62380 / ISO 26262 Part 11

FIT IEC TR 62380 / ISO 26262	FIT (Failures Per 10 <sup>9</sup> Hours) 14-pin VSON (DMT)	FIT (Failures Per 10 <sup>9</sup> Hours) 14-pin SOIC (D)	FIT (Failures Per 10 <sup>9</sup> Hours) 14-pin SOT (DYY) <sup>(1)</sup>
Total Component FIT Rate	9	18	8
Die FIT Rate	3	3	4
Package FIT Rate	6	15	4

#### Note

(1) The DYY package is only available for the TCAN1046AV-Q1

The failure rate and mission profile information in Table 2-1 comes from the Reliability data handbook IEC TR 62380 / ISO 26262 part 11:

Mission Profile: Motor Control from Table 11

Power dissipation: 250 mW
Climate type: World-wide Table 8
Package factor (lambda 3): Table 17b

Substrate Material: FR4EOS FIT rate assumed: 0 FIT

Table 2-2. Component Failure Rates per Siemens Norm SN 29500-2

Table	Category	Reference FIT Rate	Reference Virtual T <sub>J</sub>
5	CMOS, BICMOS	20 FIT	55°C
	digital, analog / mixed		

The Reference FIT Rate and Reference Virtual  $T_J$  (junction temperature) in Table 2-2 come from the Siemens Norm SN 29500-2 tables 1 through 5. Failure rates under operating conditions are calculated from the reference failure rate and virtual junction temperature using conversion information in SN 29500-2 section 4.



# 3 Failure Mode Distribution (FMD)

The failure mode distribution estimation for TCAN1046A-Q1 and TCAN1046AV-Q1 in Table 3-1 comes from the combination of common failure modes listed in standards such as IEC 61508 and ISO 26262, the ratio of sub-circuit function size and complexity and from best engineering judgment.

The failure modes listed in this section reflect random failure events and do not include failures due to misuse or overstress.

Table 3-1. Die Failure Modes and Distribution

Die Failure Modes	Failure Mode Distribution (%)
Receiver Fail	45%
Transmitter Fail	45%
CANH or CANL driver stuck dominant	5%
Short circuit any two pins	5%



## 4 Pin Failure Mode Analysis (Pin FMA)

This section provides a Failure Mode Analysis (FMA) for the pins of the TCAN1046A-Q1 and TCAN1046AV-Q1. The failure modes covered in this document include the typical pin-by-pin failure scenarios:

- Pin short-circuited to Ground (see Table 4-2)
- Pin open-circuited (see Table 4-3)
- Pin short-circuited to an adjacent pin (see Table 4-4)
- Pin short-circuited to V<sub>CC</sub> (see Table 4-6)
- Pin short-circuited to V<sub>IO</sub> (see Table 4-7)
- Pin short-circuited to V<sub>BAT</sub> (see Table 4-8)

Table 4-2 through Table 4-8 also indicate how these pin conditions can affect the device as per the failure effects classification in Table 4-1.

Table 4-1. TI Classification of Failure Effects

Class	Failure Effects
Α	Potential device damage that affects functionality
В	No device damage, but loss of functionality
С	No device damage, but performance degradation
D	No device damage, no impact to functionality or performance

Figure 4-1 shows the TCAN1046A-Q1 pin diagram, and Figure 4-3 shows the TCAN1046AV-Q1 pin diagram. For a detailed description of the device pins please refer to the *Pin Configuration and Functions* section in the TCAN1046A-Q1/TCAN1046AV-Q1 data sheet.




Figure 4-1. TCAN1046A-Q1 D Package, 14 Pin SOIC, Top View




Figure 4-2. TCAN1046A-Q1 DMT Package, 14 Pin VSON, Top View






Figure 4-3. TCAN1046AV-Q1 D Package, 14 Pin SOIC, Top View

Following are the assumptions of use and the device configuration assumed for the pin FMA in this section:

- $V_{CC} = 4.5 \text{ to } 5.5 \text{ V}$
- V<sub>BAT</sub> = 6 to 24 V
- V<sub>IO</sub> (if applicable) = 1.7 to 5.5 V

Table 4-2. Pin FMA for Device Pins Short-Circuited to Ground

Pin Name	Pin No. (TCAN 1046A- Q1)	Pin No. (TCAN 1046AV -Q1)	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	1	CAN1 will enter dominant time out mode. Unable to transmit data to the CAN1 bus.	В
GND1	2	2	None	D
V <sub>CC1</sub>	3	-	CAN1 unpowered, high I <sub>CC</sub> current.	В
V <sub>CC</sub>	-	3	Device unpowered, high I <sub>CC</sub> current.	В
RXD1	4	4	RXD default is high side FET ON, with pin short to ground, it forms direct path between supply and ground causing high current	A
TXD2	5	6	CAN2 will enter dominant time out mode. Unable to transmit data to the CAN2 bus.	В
GND2	6	5	None	D
V <sub>CC2</sub>	7	-	CAN2 unpowered, high I <sub>CC</sub> current.	В
RXD2	8	7	RXD default is high side FET ON, with pin short to ground, it forms direct path between supply and ground causing high current	А
CANL2	9	9	V <sub>O(REC)</sub> spec violated. Degraded EMC performance on CAN2 bus.	С
CANH2	10	10	Device cannot drive dominant to CAN2 bus, no communication possible.	В
STB2	11	8	STB2 stuck low, CAN2 bus unable to enter low-power mode.	В
V <sub>IO</sub>	-	11	Device will be in protected mode. Transceiver passive on both CAN1 and CAN2 bus.	В
CANL1	12	12	V <sub>O(REC)</sub> spec violated. Degraded EMC performance on CAN1 bus.	С
CANH1	13	13	Device cannot drive dominant to CAN1 bus, no communication possible.	В
STB1	14	14	STB1 stuck low, CAN1 bus unable to enter low-power mode.	В
Thermal Pad	-	-	None	D



Table 4-3. Pin FMA for Device Pins Open-Circuited

			able 4-3.1 III I MA for Device I iiis Open-onculted	
Pin Name	Pin No. (TCAN10 46A-Q1)	Pin No. (TCAN 1046AV -Q1)	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	1	TXD1 pin defaults high, CAN1 bus state always recessive and unable to transmit data to CAN1 bus.	В
GND1	2	2	CAN1 unpowered.	В
V <sub>CC1</sub>	3	-	CAN1 unpowered.	В
V <sub>CC</sub>	-	3	Device unpowered.	В
RXD1	4	4	No RXD1 output, unable to receive data from CAN1 bus.	В
TXD2	5	6	TXD2 pin defaults high, CAN2 bus state always recessive and unable to transmit data to CAN2 bus.	В
GND2	6	5	CAN2 unpowered.	В
V <sub>CC2</sub>	7	-	CAN2 unpowered.	В
RXD2	8	7	No RXD2 output, unable to receive data from CAN2 bus.	В
CANL2	9	9	Device cannot drive dominant on CAN2 bus, unable to communicate.	В
CANH2	10	10	Device cannot drive dominant on CAN2 bus, unable to communicate.	В
STB2	11	8	STB2 pin defaults high, CAN2 portion stuck in low-power mode.	В
V <sub>IO</sub>	-	11	Device will be in protected mode, Transceiver passive on both CAN1 and CAN2 bus.	В
CANL1	12	12	Device cannot drive dominant on CAN1 bus, unable to communicate.	В
CANH1	13	13	Device cannot drive dominant on CAN1 bus, unable to communicate.	В
STB1	14	14	STB1 pin defaults high, CAN1 portion stuck in low-power mode.	В
Thermal Pad	-	-	None	D

# Table 4-4. Pin FMA for Device Pins Short-Circuited to Adjacent Pin TCAN1046A-Q1

Pin Name	Pin No.	Shorted to	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	GND1	CAN1 bus will enter dominant time out mode. Unable to transmit data to CAN1 bus.	В
GND1	2	V <sub>CC1</sub>	CAN1 unpowered, high I <sub>CC</sub> current.	В
V <sub>CC1</sub>	3	RXD1	RXD1 output stuck high, unable to receive data from CAN1 bus.	В
RXD1	4	TXD2	RXD1 output reflects the input to TXD2, a separate CAN transceiver. Information from CAN1 will not be received correctly.	В
TXD2	5	GND2	CAN2 bus will enter dominant time out mode. Unable to transmit data to CAN2 bus.	В
GND2	6	V <sub>CC2</sub>	CAN2 unpowered, high I <sub>CC</sub> current.	В
RXD2	8	CANL2	Messages on RXD2 will be corrupted by CANL2. Reception of data from CAN2 bus will not be possible. I <sub>OS</sub> current may be reached.	В
CANL2	9	CANH2	CAN2 bus stuck recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH2	10	STB2	CAN2 driver and receiver turn off when a dominant is driven on CAN2 bus. May not enter normal mode.	В
STB2	11	CANL1	CAN2 driver and receiver may turn off when the CAN1 bus is recessive. May not enter normal mode.	В
CANL1	12	CANH1	CAN1 bus stuck recessive, no communication possible I <sub>OS</sub> current may be reached.	В
CANH1	13	STB1	CAN1 driver and receiver turn off when a dominant is driven on CAN1 bus. May not enter normal mode.	В



#### Note

The VSON package includes a thermal pad. All device pins are adjacent to the thermal pad. The device behavior when pins are shorted to the thermal pad depends on which net is connected to the thermal pad.

Table 4-5. Pin FMA for Device Pins Short-Circuited to Adjacent Pin TCAN1046AV-Q1

Pin Name	Pin No.	Shorted to	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	GND1	CAN1 bus will enter dominant time out mode. Unable to transmit data to CAN1 bus.	В
GND1	2	V <sub>CC</sub>	Device unpowered, high I <sub>CC</sub> current.	В
V <sub>CC</sub>	3	RXD1	RXD1 output stuck high, unable to receive data from CAN1 bus.	В
RXD1	4	GND2	RXD default is high side FET ON, with pin short to ground, it forms direct path between supply and ground causing high current	А
GND2	5	TXD2	CAN2 bus will enter dominant time out mode. Unable to transmit data to CAN2 bus.	В
TXD2	6	RXD2	RXD2 output reflects the input to TXD2, and while this is the same transceiver, due to loop delay, the communication will be corrupted. Information from CAN2 bus will not be received correctly.	В
STB2	8	CANL2	CAN2 driver and receiver may turn off when the CAN2 bus is recessive. May not enter normal mode.	В
CANL2	9	CANH2	CAN2 bus stuck recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH2	10	V <sub>IO</sub>	CAN2 bus stuck dominant, no communication possible.	В
V <sub>IO</sub>	11	CANL1	CAN1 bus stuck recessive, no communication possible. I <sub>OS</sub> current may be reached on CANL1.	В
CANL1	12	CANH1	CAN1 bus stuck recessive, no communication possible I <sub>OS</sub> current may be reached.	В
CANH1	13	STB1	CAN1 driver and receiver turn off when a dominant is driven. May not enter normal mode.	В

### Table 4-6. Pin FMA for Device Pins Short-Circuited to $V_{\text{CC}}$

Pin Name	Pin No. (TCAN10 46A-Q1)	Pin No. (TCAN 1046AV -Q1)	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	1	TXD1 pin stuck high, unable to transmit data to CAN1 bus.	В
GND1	2	2	CAN1 transceiver unpowered, high I <sub>CC</sub> current.	В
V <sub>CC1</sub>	3	-	None	D
V <sub>CC</sub>	-	3	None	D
RXD1	4	4	RXD1 pin stuck high, unable to receive data from CAN1 bus.	В
TXD2	5	6	TXD2 pin stuck high, unable to transmit data to CAN2 bus.	В
GND2	6	5	CAN2 transceiver unpowered, high I <sub>CC</sub> current.	В
V <sub>CC2</sub>	7	-	None	D
RXD2	8	7	RXD2 pin stuck high, unable to receive data for CAN2 bus.	В
CANL2	9	9	CAN2 bus always recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH2	10	10	V <sub>O(REC)</sub> spec violated, degraded EMC performance on CAN2 bus.	С
STB2	11	8	STB2 stuck high, CAN2 transceiver always in standby mode.	В
V <sub>IO</sub>	-	11	IO pins will operate as 5V input/output. Microcontroller may be damaged if $V_{CC} > V_{IO}$ .	С
CANL1	12	12	CAN1 bus always recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH1	13	13	V <sub>O(REC)</sub> spec violated, degraded EMC performance on CAN1 bus.	С
STB1	14	14	STB1 stuck high, CAN1 transceiver always in standby mode.	



Table 4-7. PIN FMA for Device Pins Short-Circuited to V<sub>IO</sub>

Pin Name	Pin No. (TCAN10 46AV-Q1)	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	TXD1 stuck high, unable to transmit data to CAN1 bus.	В
GND1	2	CAN1 unpowered, high I <sub>IO</sub> current.	В
V <sub>CC</sub>	3	IO pins will operate as 5V input/output. Microcontroller may be damaged if $V_{CC} > V_{IO}$ .	С
RXD1	4	RXD1 pin stuck high, unable to receive data from CAN1 bus.	В
GND2	5	CAN2 unpowered, high I <sub>IO</sub> current.	В
TXD2	6	TXD2 stuck high, unable to transmit data to CAN2 bus.	В
RXD2	7	RXD2 pin stuck high, unable to receive data from CAN2 bus.	В
STB2	8	STB2 stuck high, CAN2 transceiver always in standby mode.	В
CANL2	9	CAN2 bus always recessive, no communication possible. $I_{OS}$ current may be reached if $V_{IO} \ge 3.3$ V.	В
CANH2	10	$V_{O(REC)}$ spec violated if $V_{IO} \ge 3.3V$ , degraded EMC performance on CAN2 bus.	С
$V_{IO}$	11	None	D
CANL1	12	CAN1 bus always recessive, no communication possible. $I_{OS}$ current may be reached if $V_{IO} \ge 3.3$ V.	В
CANH1	13	$V_{O(REC)}$ spec violated if $V_{IO} \ge 3.3V$ , degraded EMC performance on CAN1 bus.	С
STB1	14	STB1 stuck high, CAN1 transceiver always in standby mode.	В

Table 4-8. Pin FMA for Device Pins Short-Circuited to V<sub>BAT</sub>

Pin Name	Pin No. (TCAN10 46A-Q1)	Pin No. (TCAN 1046AV -Q1)	Description of Potential Failure Effect(s)	Failure Effect Class
TXD1	1	1	Absolute maximum violation, transceiver may be damaged. Unable to transmit data to CAN1 bus.	А
GND1	2	2	Device unpowered, high I <sub>BAT</sub> current.	В
V <sub>CC1</sub>	3	-	Absolute maximum violation, transceiver may be damaged. CAN1 bus may be unable to communicate.	Α
V <sub>CC</sub>	-	3	Absolute maximum violation, transceiver may be damaged. CAN bus may be unable to communicate.	А
RXD1	4	4	Absolute maximum violation, transceiver may be damaged. Unable to receive data from CAN1 bus.	А
TXD2	5	6	Absolute maximum violation, transceiver may be damaged. Unable to transmit data to CAN2 bus.	А
GND2	6	5	Device unpowered, high I <sub>BAT</sub> current.	В
$V_{CC2}$	7	-	Absolute maximum violation, transceiver may be damaged. CAN2 bus may be unable to communicate.	А
RXD2	8	7	Absolute maximum violation, transceiver may be damaged. Unable to receive data from CAN2 bus.	В
CANL2	9	9	CAN2 bus always recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH2	10	10	V <sub>O(REC)</sub> spec violated, degraded EMC performance on CAN2 bus.	С
STB2	11	8	Absolute maximum violation, transceiver may be damaged. CAN2 transceiver stuck in standby mode.	А
V <sub>IO</sub>	-	11	Absolute maximum violation, transceiver may be damaged.	Α
CANL1	12	12	CAN1 bus always recessive, no communication possible. I <sub>OS</sub> current may be reached.	В
CANH1	13	13	V <sub>O(REC)</sub> spec violated, degraded EMC performance on CAN1 bus.	В
STB1	14	14	Absolute maximum violation, transceiver may be damaged. CAN1 transceiver stuck in standby mode.	А

Instruments Revision History www.ti.com

# **5 Revision History**

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

DATE	REVISION	NOTES
October 2021	*	Initial Release

#### IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATA SHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.

TI objects to and rejects any additional or different terms you may have proposed.

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2022, Texas Instruments Incorporated